

Final Reclamation and Stormwater Inspection

Date: 04/10/2023

Operator: CIVITAS NORTH LLC - 10661

Location ID: 455825

Inspection Document #: 708200120

Weld County, CO

SWSW Section 20 T8N R59W

Dylan Edwardson
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Wade 8-59-20A
Location ID: 455825



Photo 1. Facing North from the proposed location. Operator submitted a Form 4 Sundry Notices stating the wells were not drilled. The Form 2A (Doc #401485605) expired on 07/07/2021. Location was not constructed at the proposed well locations based off field observations. No evidence of oil and gas activities.

Inspection Photos
Location Name: Wade 8-59-20A
Location ID: 455825



Photo 2. Facing east; see comments in Photo 1.

Inspection Photos
Location Name: Wade 8-59-20A
Location ID: 455825



Photo 3. Facing south; see comments in Photo 1.

Inspection Photos
Location Name: Wade 8-59-20A
Location ID: 455825



Photo 4. Facing west; see comments in Photo 1.