

Inspection Photos

April 5, 2023

Operator: Mustang Resources LLC - #10550

Location ID: 322325

Location Name: JUHAN RULISON UNIT-66S94W/34NESW

Inspection Document #: 702801442

Garfield County, CO

NESW Section 34 T6S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: JUHAN RULISON UNIT-
66S94W/34NESW
Location ID: 322325



Photo 1. Photo taken from the west shows an overview of the location.

Inspection Photos
Location Name: JUHAN RULISON UNIT-
66S94W/34NESW
Location ID: 322325



Photo 2. Photos show lack of pad stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801442

Inspection Photos
Location Name: JUHAN RULISON UNIT-
66S94W/34NESW
Location ID: 322325



Photo 3. Photos show examples of interim areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801442