

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



Photo # 4991 From entrance to location



Photo # 4992 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



Photo # 4993 Location



Photo # 4994 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



Photo # 3905 From Inspection 708900197 conducted on 03/31/2023 Meter calibration info not conspicuously posted

Photo # 4995 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 67-20 pad

Location ID: 335289



Photo # 3904 From Inspection 708900197 conducted on 03/31/2023 Meter calibration info not conspicuously posted



Photo # 4996 Meter calibration info not conspicuously posted