

# Interim Reclamation and Stormwater Inspection

Date: 04/10/2023

Operator: NOBLE ENERGY INC - 100322

Location ID: 330957

Inspection Document #: 708200124

Weld County, CO

NWNE Section 29 T8N R59W

Dylan Edwardson  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Wade-68N58W 29NWNE  
Location ID: 330957



**Photo 1.** Facing northeast from the southern portion of the location. At the time of this inspection, this location meets Rule 1003 vegetative standards. Desirable, perennial establishment is evident throughout the interim areas and is reflective of reference area vegetation.

Inspection Photos  
Location Name: Wade-68N58W 29NWNE  
Location ID: 330957



**Photo 2.** Facing north; see comments in Photo 1.

Inspection Photos  
Location Name: Wade-68N58W 29NWNE  
Location ID: 330957



**Photo 3.** Facing northwest from the eastern/center portion. See comments in Photo 1.

Inspection Photos  
Location Name: Wade-68N58W 29NWNE  
Location ID: 330957



**Photo 4.** Facing southeast from the western/center portion. See comments in Photo 1.

Inspection Photos

Location Name: Wade-68N58W 29NWNE

Location ID: 330957



**Photos 5 & 6.** Tumbleweed accumulations should be managed for in the future.