

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 213-20 pad

Location ID: 335335



Photo # 4934 From entrance to location



Photo # 4935 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 213-20 pad

Location ID: 335335



Photo # 4938 Stained soils & gravel



Photo # 4942 Debris

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RMV 213-20 pad

Location ID: 335335



Photo # 4944 Debris



Photo # 4945 Debris