

**KT Resources LLC
Ant Hill unit 21-22
Location #398705**



Lease road off county road 143



Entrance to location

**KT Resources LLC
Ant Hill unit 21-22
Location #398705**



Chemical tank labels missing and/or illegible



Containment full of liquid waste

**KT Resources LLC
Ant Hill unit 21-22
Location #398705**



Sign at tank battery



Chemical tank labels missing and/or illegible

**KT Resources LLC
Ant Hill unit 21-22
Location #398705**



Containment full of liquid waste



Sediment movement and migration

**KT Resources LLC
Ant Hill unit 21-22
Location #398705**



Sediment migration down lease road



Sediment migration through berm erosion