

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203

Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403370720

Receive Date:

Report taken by:

Site Investigation and Remediation Workplan (Supplemental Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>PETROSHARE CORPORATION</u>	Operator No: <u>10454</u>	Phone Numbers
Address: <u>9635 MAROON CIRCLE #400</u>		Phone: <u>(303) 894-2100 x5181</u>
City: <u>ENGLEWOOD</u>	State: <u>CO</u>	Zip: <u>80112</u>
Contact Person: <u>James Hix - East OWP EPS</u>	Email: <u>james.hix@state.co.us</u>	Mobile: <u>(303) 905-5341</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 20820 Initial Form 27 Document #: 402872459

PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☐ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☒ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☒ Other: Nordman (OWP) 41-20: PA Well Venting Gas.

SITE INFORMATION

No Multiple Facilities

Facility Type: <u>WELL</u>	Facility ID: <u></u>	API #: <u>039-06553</u>	County Name: <u>ELBERT</u>
Facility Name: <u>NORDMAN TRUST 41-20</u>		Latitude: <u>39.518969</u>	Longitude: <u>-104.572019</u>
		** correct Lat/Long if needed: Latitude: <u></u>	Longitude: <u></u>
QtrQtr: <u>NENE</u>	Sec: <u>20</u>	Twp: <u>6S</u>	Range: <u>64W</u>
		Meridian: <u>6</u>	Sensitive Area? <u>Yes</u>

SITE CONDITIONS

General soil type - USCS Classifications SM Most Sensitive Adjacent Land Use Pasture - Rangeland

Is domestic water well within 1/4 mile? No Is surface water within 1/4 mile? Yes

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

08/10/2021 ~1320 ft North: 45101 CR 21 Elizabeth, CO 80107, DWR Water Well Permit Application Hold, Domestic, Stock. Proposed Depth (T) 250; Depth (B) 435. Lower Dawson, Yield = 15 Receipt 10014420; Running Creek

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ E&P Waste ☒ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☒ Oil ☐ Tank Bottoms
- ☐ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☒ Other (as described by EPA) E&P Debris - Well Plugging and Abandonment

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	SOILS	Unknown	Visually, Sampling

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Emergency Response Measure to plug and abandon (PA) The Nordman Trust (OWP) 41-20 well venting gas.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

If impacted soils are encountered during PA activities, one or more soil samples will be collected for analysis of Table 915-1 parameters. Inspection photographs taken on 11/9/2021 do not show stained soils around the wellhead.

Proposed Groundwater Sampling

☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Groundwater is not expected to be encountered during the PA operations for the Nordman (OWP) 41-20 well . Groundwater samples are not expected to be collected during the PA operations; however, collection of groundwater samples may be evaluated during subsequent operations if soil samples exceed Table 915-1 concentrations/levels and pending further review of the depth to shallow groundwater.

Proposed Surface Water Sampling

☒ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Surface water samples are not expected to be collected during the PA operations for the Nordman (OWP) 41-20 well.

Additional Investigative Actions

☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Additional alternative investigative actions are not expected to be warranted during the PA operations for the Nordman (OWP) 41-20.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

NA / ND

Number of soil samples collected 5

Number of soil samples exceeding 915-1 2

Was the areal and vertical extent of soil contamination delineated? No

Approximate areal extent (square feet) 144

-- Highest concentration of TPH (mg/kg) 5390

-- Highest concentration of SAR 2

BTEX > 915-1 Yes

Vertical Extent > 915-1 (in feet) 4

Groundwater

Number of groundwater samples collected 0

Was extent of groundwater contaminated delineated? No

Depth to groundwater (below ground surface, in feet)

Number of groundwater monitoring wells installed

Number of groundwater samples exceeding 915-1

Highest concentration of Benzene (µg/l)

Highest concentration of Toluene (µg/l)

Highest concentration of Ethylbenzene (µg/l)

Highest concentration of Xylene (µg/l)

Highest concentration of Methane (mg/l)

Surface Water

0 Number of surface water samples collected

Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards)

Volume of liquid waste (barrels)

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

Does this Supplemental Form 27A include changes to a previously approved Remedial Action Plan? No

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

Source removal is not expected at this time. The OWP well was found to be leaking gas on 11/16/2021. The Nordman Trust (OWP) #41-20 will be PA to stop the well from venting gas. Associated flowlines will be decommissioned at a later date.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

No staining was observed around the Nordman Trust (OWP) #41-20 on 11/16/2021. If impacted soils are encountered during subsequent flowline decommissioning the soil will be excavated, removed, and hauled to a commercial disposal facility.

Soil Remediation Summary

☐ In Situ

☐ Ex Situ

Bioremediation (or enhanced bioremediation)

Chemical oxidation

Air sparge / Soil vapor extraction

Excavate and offsite disposal

If Yes: Estimated Volume (Cubic Yards)

Name of Licensed Disposal Facility or COGCC Facility ID #

_____ Natural Attenuation

_____ Other _____

_____ Excavate and onsite remediation

_____ Land Treatment

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)

_____ Chemical oxidation

_____ Air sparge / Soil vapor extraction

_____ Natural Attenuation

_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDIATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

☐ Quarterly☐ Semi-Annually☐ Annually☒ Other

☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☐ Other

Adequacy of Operator's General Liability Insurance and Financial Assurance

Describe the adequacy of the Operator's general liability insurance and Financial Assurance to fully address the anticipated costs of Remediation, including the estimated remaining cost for this project (below).

If this information has been provided on a Form 27 within the last 12 months, provide the Document Number of that form.

The PETROSHARE CORPORATION - 10454 NORDMAN TRUST (OWP) #41-20 well and NORDMAN TRUST-66S64W 20NENE (Location ID #322194) are in the COGCC Orphaned Well Program.

Operator anticipates the remaining cost for this project to be: \$

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation?

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

REMEDIATION COMPLETION REPORT

REMEDIATION COMPLETION SUMMARY

Is this a Final Closure Request for this Remediation Project? No

If YES:

☐ Compliant with Rule 913.h.(1).☐ Compliant with Rule 913.h.(2).☐ Compliant with Rule 913.h.(3).

Do all soils meet Table 915-1 standards?

Does the previous reply indicate consideration of background concentrations?

Does Groundwater meet Table 915-1 standards?

Is additional groundwater monitoring to be conducted? _____

Operator shall comply with the COGCC 1000-Series Reclamation Requirements for all impacted and disturbed areas.

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

The Nordman Trust (OWP) #41-20 well pad will be reclaimed at a later date, once flowlines have been decommissioned. Reclamation will consist of installing stormwater controls, scarifying the surface, preparing a seed bed, and re-seeding the location with a native seed mix or suitable seed mix approved by the surface owner.

Is the described reclamation complete? _____

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim

☐ Final

Did the Surface Owner provide the seed mix? _____

If YES, does the seed mix comply with local soil conservation district recommendations? _____

Did the local soil conservation district provide the seed mix? _____

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation. _____

Proposed date of completion of Reclamation. _____

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. _____

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 11/16/2021

Proposed site investigation commencement. _____

Proposed completion of site investigation. _____

REMEDIAL ACTION DATES

Proposed start date of Remediation. _____

Proposed date of completion of Remediation. _____

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

The PETROSHARE CORP. - 10454 NORDMAN TRUST (OWP) #41-20 oil and gas location and off-location flowline are in the COGCC Orphaned Well Program. This supplemental Form 27 presents the results of site investigation activities performed during the wellhead plugging and abandonment and off-location flowline removal. Additional site investigation and remediation are warranted at the NORDMAN TRUST (OWP) #41-20 wellhead and flowline impacts to meet Table 915-1 concentrations. Completion information for DWR Water Well Permit #328100 located approximately 1875 ft north, indicates a total depth of 395 ft, perforated casing from 215 ft to 395 ft, a static water level of 180 ft, yield of 6 - 8 gpm, and completed in the lower Dawson aquifer.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: James Hix

Title: East OWP EPS

Submit Date: _____

Email: james.hix@state.co.us

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: _____

Date: _____

Remediation Project Number: 20820

COA Type**Description**

0 COA	

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

Att Doc Num**Name**

403370722	SITE INVESTIGATION REPORT
403370724	SITE INVESTIGATION REPORT

Total Attach: 2 Files

General Comments**User Group****Comment****Comment Date**

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)