

Inspection Photos

April 10, 2023

Operator: TEP Rocky Mountain- #96850

Location ID: 417271

Location Name: Federal/KP 33-18

Inspection Document #: 702801452

Garfield County, CO

NWSE Section 18 T6S R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Federal/KP 33-18
Location ID: 417271



Photo 1. Photo taken from the entrance shows an overview of the location.



Inspection Photos
Location Name: Federal/KP 33-18
Location ID: 417271



Photo 2. Photos show production areas.



Inspection Photos
Location Name: Federal/KP 33-18
Location ID: 417271



Photo 3. Photos show production areas (left) and a load line without a bull plug installed (right).



Inspection Photos
Location Name: Federal/KP 33-18
Location ID: 417271



Photo 4. Photos show List B Noxious weeds houndstongue (left) Scotch thistle (right).



Inspection Photos
Location Name: Federal/KP 33-18
Location ID: 417271



Photo 5. Photos show the List B Noxious weed Scotch thistle.



Inspection Photos
Location Name: Federal/KP 33-18
Location ID: 417271



Photo 6. Photos shows where stormwater from the eastern ditch is breaking through the berm (left) and causing degradation to interim areas below (right).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801452

Inspection Photos
Location Name: Federal/KP 33-18
Location ID: 417271



Photo 7. Photos shows interim areas to the southwest (left) and northwest (right).



Inspection Photos
Location Name: Federal/KP 33-18
Location ID: 417271



Photo 8. Photos shows interim areas to the north (left) and east (right).

