

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 5-21 Pad

Location ID: 323888



Photo # 5326 From entrance to location



Photo # 5327 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 5-21 Pad

Location ID: 323888



Photo # 5328 Location



Photo # 5330 Meter calibration info not conspicuously posted



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 5-21 Pad

Location ID: 323888



Photo # 5333 Unmarked deadman