

Inspection Photos
Location Name: Wolf 35-2623H
Location ID: 428753



Photo 1 – ECD



Photo 2 – Tank Battery

Inspection Photos
Location Name: Wolf 35-2623H
Location ID: 428753



Photo 3 – Tank Battery Sign



Photo 4 – Unused Pipe on West Side of Location

Inspection Photos
Location Name: Wolf 35-2623H
Location ID: 428753



Photo 5 – Unmarked Risers



Photo 6 – Unmarked Risers

Inspection Photos
Location Name: Wolf 35-2623H
Location ID: 428753



Photo 7 – Flares



Photo 8 – Wellhead

Inspection Photos
Location Name: Wolf 35-2623H
Location ID: 428753



Photo 9 – Wellhead Sign – Stained Soil



Photo 10 – Stained Soil at Exhaust

Inspection Photos
Location Name: Wolf 35-2623H
Location ID: 428753



Photo 11 – Gas Engine – Stained Soil