

Caerus Piceance LLC
PCU T64X-8G
Location # 316302



Location



location

Caerus Piceance LLC
PCU T64X-8G
Location # 316302



Location



location

Caerus Piceance LLC
PCU T64X-8G
Location # 316302



Apr 10, 2023 at 11:41:37 AM
+39.890945,-108.189482 ±4.79r
COGCI



Apr 10, 2023 at 11:42:35 AM
+39.890898,-108.189594 ±4.74r
COGCI

Tank signage has different operator information

Trash can in containment with unknown sediment and not labeled

Caerus Piceance LLC
PCU T64X-8G
Location # 316302



Trash can in containment with unknown sediment and not labeled



Trash can in containment with unknown sediment and not labeled

Caerus Piceance LLC
PCU T64X-8G
Location # 316302



Access entrance to location shows some signs of lack of stabilization



Location shows some signs of lack of stabilization



Caerus Piceance LLC
PCU T64X-8G
Location # 316302



Sediment being pushed off of location



Sediment being pushed off of location

Caerus Piceance LLC
PCU T64X-8G
Location # 316302



Sediment being pushed off of location



Sediment being pushed off of location