

**KT Resources  
AHU 29-11  
Location # 316309**



**Location lacks BMP's to prevent sediment migration  
shown in multiple photos**



**Tank battery signage is lacking information**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

KT Resources  
AHU 29-11  
Location # 316309



location



location



**KT Resources**  
**AHU 29-11**  
**Location # 316309**



**location**



**Location and well signage is lacking information**





**KT Resources**  
**AHU 29-11**  
**Location # 316309**



**Staining**



**Weeds have turned into debris**





**KT Resources**  
**AHU 29-11**  
**Location # 316309**



**Weeds have turned into debris**



**Dead man not marked properly**





KT Resources  
AHU 29-11  
Location # 316309



Unused/ stored equipment



Unused/ stored equipment





**KT Resources  
AHU 29-11  
Location # 316309**



**Unused/ stored equipment**



**Containment is full of fluid**

**KT Resources**  
**AHU 29-11**  
**Location # 316309**



**Access road graveled**

