

Inspection Photos
Location Name: KREPS TRUST-66N64W/6SWSE
Location #: 332020



Photo #1
Kreps Trust 34-6 (123-21723) Wellsite
Producing | PR



Photo #2
Kreps Trust 34-6, 44-6, Kreps 24-6, 33-6, 44-6
Battery site
Active

Inspection Photos

Location Name: KREPS TRUST-66N64W/6SWSE

Location #: 332020



Photo #3

Kreps Trust 34-6, 44-6, Kreps 24-6, 33-6, 44-6

Battery site

Active

Tank(s): SE corner



Photo #4

Kreps Trust 34-6, 44-6, Kreps 24-6, 33-6, 44-6

Battery site

Active

Separator(s), Compressor

Inspection Photos

Location Name: KREPS TRUST-66N64W/6SWSE

Location #: 332020



Photo #5

Kreps Trust 34-6, 44-6, Kreps 24-6, 33-6, 44-6

Battery site

Active

ECD(s)



Photo #6

Kreps Trust 34-6, 44-6, Kreps 24-6, 33-6, 44-6

Battery site

Active

Battery sign(s)

Location #: 332020

Last documented calibration date: 11-10-2021