

CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location # 335687



Wellheads – Photo #02155



Separators – Photo #02160

CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location # 335687



Tank Battery – Photo #02163



Water Tank – Photo #02173

CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location # 335687



Pig Station – Photo #02172



Casing Flange Leak – Photo #02157

CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location # 335687



Sediment Transport from Lease Road – Photo #02171



Slope Erosion into Lease Road Ditch – Photo #02178

CAERUS PICEANCE LLC, UNOCAL-66S96W/9SWSW

Location # 335687



Lack of Stabilization – Photo #02159

Lack of Stabilization – Photo #02162