

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 7-21 Pad

Location ID: 323900



Photo # 5233 From entrance to location



Photo # 5234 Location

**Inspection Photos**  
**Location Name: TEP ROCKY MOUNTAIN LLC RMV 7-21 Pad**  
**Location ID: 323900**



**Photo # 5235 Location**

**Photo # 5241 Location**

Inspection Photos  
Location Name: TEP ROCKY MOUNTAIN LLC RMV 7-21 Pad  
Location ID: 323900



**Photo # 5236 Meter calibration info not conspicuously posted**

**Photo # 5237 Meter calibration info not conspicuously posted**

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 7-21 Pad

Location ID: 323900



Photo # 5239 Open ended pipe on top of production tank