

Inspection Photos

April 10, 2023

Operator: TEP Rocky Mountain- #96850

Location ID: 335209

Location Name: Jolley/KP 22-21

Inspection Document #: 702801467

Garfield County, CO

SENW Section 21 T6S R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Jolley/KP 22-21
Location ID: 335209



Photo 1. Photo taken from the entrance shows an overview of the location.

Inspection Photos
Location Name: Jolley/KP 22-21
Location ID: 335209



Photo 2. Photos show production areas.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801467

Inspection Photos
Location Name: Jolley/KP 22-21
Location ID: 335209



Photo 3. Photos show bull plugs not installed on a tank drain line (left) and a load line (right).



Inspection Photos
Location Name: Jolley/KP 22-21
Location ID: 335209




Photo 4. Photo shows fencing in disrepair.

Inspection Photos
Location Name: Jolley/KP 22-21
Location ID: 335209



Photo 5. Photo shows concrete equipment no longer in use.



Inspection Photos
Location Name: Jolley/KP 22-21
Location ID: 335209



Photo 6. Photo shows what appears to be interim areas at the north of the location.