

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 242-21 Pad

Location ID: 335101



Photo # 5364 From entrance to location



Photo # 5365 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 242-21 Pad

Location ID: 335101



Photo # 5367 Stained soils & gravel



Photo # 5368 Stained soils & gravel

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 242-21 Pad

Location ID: 335101



Photo # 5370 Stained soils & gravel