

Inspection Photos

API: 071-06324

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/13/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06324 | Date: 4/13/2023

Inspection Photos



Photo 1. Facing south toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06324 | Date: 4/13/2023

Inspection Photos



Photo 2. Stormwater is cutting underneath the rip/rap in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06324 | Date: 4/13/2023

Inspection Photos



Photo 3. There is degraded unused shed that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06324 | Date: 4/13/2023