

Inspection Photos

API: 071-06823

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 4/13/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06823 | Date: 4/13/2023

Inspection Photos



Photo 1. Facing toward the wellsite.



Inspection Photos



Photo 2. The vegetation is well established along the fill slope for stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06823 | Date: 4/13/2023

Inspection Photos



Photo 3. Facing toward the wellsite.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06823 | Date: 4/13/2023