

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/05/2023

Submitted Date:

04/17/2023

Document Number:

711800003

FIELD INSPECTION FORM

Loc ID: 322172 Inspector Name: Jacobson, Eric On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 70385
Name of Operator: SMITH ENERGY CORP
Address: 12706 SHILOH RD
City: GREELEY State: CO Zip: 80631

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Diane McCoy		Diane.mccoy@state.co.us	
Diana Burn		Diana.burn@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
209478	WELL	DG	03/29/2023	GW	039-06383	COGGINS ET AL 1-10 (OWP)	SI

General Comment:

Cold and snowy

Inspected Facilities

Facility ID: 209478 Type: WELL API Number: 039-06383 Status: DG Insp. Status: SI

Cement

Cement Contractor

Contractor Name: American

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): 7405

Cement Volume (sx): 40

Good Return During Job: _____

Cement Type: Class G

Comment:

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
Perf at 77475' CICR at 7405' Cement with 40 sacks	jacobsoe	04/17/2023
GMT plugging an OWP well which is offset to the GMt Vulcan pad		