

Interim Reclamation and Stormwater Inspection

April 7, 2023

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462908

Inspection Document #: 697504599

Weld County, CO

NESE Section 21 T11N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Little Lady 21/North Well Pad

Location ID: 462908



Photo 1. Photo taken from the southeastern location, facing South. Photo illustrates trash being stored on location has been removed.



Photo 2. Photo taken from the southeastern location, facing North. See comments under Photo 1.

Note- weeds were observed along the eastern perimeter of location, which still need to be addressed. Also, interim reclamation remains out of compliance.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 697504599