

# Interim Reclamation and Stormwater Inspection

April 7, 2023

Operator: UPLAND EXPLORATION LLC- #10701

Location ID: 462919

Inspection Document #: 697504601

Weld County, CO

SESE Section 21 T11N R64W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

**Inspection Photos**  
**Location Name: Little Lady 21/South Well Pad**  
**Location ID: 462919**



**Photo 1.** Photo taken from the eastern location, facing Northeast. Photo illustrates all unused equipment has been removed.

Note- weeds were observed along the eastern perimeter of location, which still need to be addressed. Also, interim reclamation remains out of compliance.



**Photo 2.** Photo taken from the eastern location, facing North. Photo illustrates a spill from non-E&P exempt waste previously believed to be from a Mobil Pegasus SAE 40 container but was related to the compressor has been cleaned up.





Inspection Photos  
Location Name: Little Lady 21/South Well Pad  
Location ID: 462919



**Photo 3.** Photo taken from the eastern location, facing East. Photo illustrates stained soil/spill related to the compressor has been cleaned up and additional gravel imported.



**Photo 4.** Photo taken from the eastern location, facing East. Photo illustrates COGCC staff checking to ensure stained soil/spill was cleaned up.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 697504601



Inspection Photos  
Location Name: Little Lady 21/South Well Pad  
Location ID: 462919



**Photo 5.** Photo taken from the eastern location, facing North.  
Photo illustrates netting has been repaired.



**Photo 6.** Photo taken from the eastern location, facing North.  
Photo illustrates fluids have been removed and disposed of.





Inspection Photos  
Location Name: Little Lady 21/South Well Pad  
Location ID: 462919



**Photo 7.** Photo taken from within the secondary containment, illustrating oily waste. Remove and properly dispose fluids from within the secondary containment.



**Photo 8.** Photo taken from within the secondary containment, illustrating a hose being stored within secondary containment. COGCC staff communicated that this is considered unused equipment and needs to be removed.