

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 331-21 Pad

Location ID: 335179



Photo # 5374 From entrance to location



Photo # 5375 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC CLOUGH RWF 331-21 Pad

Location ID: 335179



Photo # 5376 Stained soils & gravel



Photo # 5377 Stained soils & gravel