

**KT Resources
Federal M30-2-96N
Location # 315898**



Tank battery



Horizontal separator

**KT Resources
Federal M30-2-96N
Location # 315898**



Meter house



Open top tank

KT Resources
Federal M30-2-96N
Location # 315898



Open cellar



Open cellar

**KT Resources
Federal M30-2-96N
Location # 315898**



Chemical tank containment is full and wildlife protection insufficient



Chemical tank containment is full and wildlife protection insufficient

**KT Resources
Federal M30-2-96N
Location # 315898**



Chemical tank label fading



Open top tank



**KT Resources
Federal M30-2-96N
Location # 315898**



Some staining



Access road lacks sufficient BMP's

**KT Resources
Federal M30-2-96N
Location # 315898**



Lack of stabilization/compaction



Access road lacks sufficient BMP's

**KT Resources
Federal M30-2-96N
Location # 315898**



Sediment migration from access road



Access road lacks sufficient BMP's

**KT Resources
Federal M30-2-96N
Location # 315898**



Sediment migration from access road



Access road lacks sufficient BMP's

**KT Resources
Federal M30-2-96N
Location # 315898**



Access road lacks sufficient BMP's

