

Interim Reclamation and Stormwater Inspection

April 12, 2023

Operator: EDGE ENERGY II LLC- #10671

Location ID: 456286

Inspection Document #: 697504603

Weld County, CO

NENE Section 29 T11N R66W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 1. Photo taken along a portion of the southern interim reclamation area, facing North. Photo illustrates Cereal rye that appears to have gone to seed throughout the eastern and southern interim reclamation areas. Operator indicated that additional seeding would be performed within the next week.



Photo 2. Photo taken from the central interim reclamation area, facing Southeast. See comments under Photo 1.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 3. Photo taken from the well location, facing West. During an inspection with the Operator on 4/12/23, it was stated that this would be equipment used to build a shed.



Photo 4. Photo taken from the northern interim reclamation area, facing Southeast. There did not appear to be any establishment of Cereal rye along the northern perimeter.

Inspection Photos
Location Name: Deporter /29-A Pad
Location ID: 456286



Photo 5. Photo taken from the western topsoil stockpile, facing North. Photo illustrates the lack of stabilization and prevention of weed establishment. See comments under Photo 1.



Photo 6. Photo taken from within the secondary containment of oily waste that needs to be removed and properly disposed of.