


**Peterson Energy Operating, Inc.  
Photo Log 10/11/2022 Pictures**



Impacted area, thriving green vegetation

Unimpacted area, dead brown vegetation

**Green grass west of the Church 41B-25 three weeks after the spill demonstrating enhanced growth in the impacted area.**



**Green grass northwest of the Church 41B-25 three weeks after the spill demonstrating enhanced growth in the impacted area.**