

Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306



Photo 1 – Wellhead – Stained Soil

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306



Photo 3 –Pumping Unit

Photo 4 – Stained Soil

Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306



Photo 5 – Stained Soil at Gas Engine



Photo 6 – Stained Soil at Gas Engine

Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306



Photo 7 – Stained Soil at Exhaust



Photo 8 – Weeds in I.R. Area

Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306



Photo 9 – Weeds in I.R. Area



Photo 10 – Weeds in I.R. Area

Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306



Photo 11 – Weeds in I.R. Area



Photo 12 – Weeds in I.R. Area

Inspection Photos
Location Name: Wildhorse 18-1834H
Location ID: 430306



Photo 13 – Weeds in I.R. Area



Photo 14 – Weeds in I.R. Area