

Inspection Photos
Location Name: Washburn LE 22-78HN
Location ID: 427642




Photo 1 – Wellhead



Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Washburn LE 22-78HN
Location ID: 427642



Photo 3 – Pumping Unit



Photo 4 – Gas Meters and ECDs

Inspection Photos
Location Name: Washburn LE 22-78HN
Location ID: 427642



Photo 5 – Heater Treater



Photo 6 – Tank Battery – Tumbleweeds

Inspection Photos
Location Name: Wildhorse 18-1844H
Location ID: 430327



Photo 7 – Tumbleweeds



Photo 8 – NFPA Label

Inspection Photos
Location Name: Washburn LE 22-78HN
Location ID: 427642



Photo 9 – Tank Battery



Photo 10 – Tumbleweeds

