

Inspection Photos
Location Name: McDonald Unit 2
Location ID: 336356



Photo 1 WH sign.

Photo 2 Stained soil around the WH.

Inspection Photos
Location Name: McDonald Unit 2
Location ID: 336356



Photo 3 Pump Jack.



Photo 4 Dead weeds around the transformers.