

Inspection Photos
Location Name: Thomas L. Russell A 2
Location ID: 318279



Photo 1 WH sign.

Photo 2 WH.

Inspection Photos
Location Name: Thomas L. Russell A 2
Location ID: 318279



Photo 3 Pump Jack.

Photo 4 ancillary equip.

Inspection Photos
Location Name: Thomas L. Russell A 2
Location ID: 318279



Photo 5 TB sign.

Photo 6 TB

Inspection Photos
Location Name: Thomas L. Russell A 2
Location ID: 318279



Photo 7 Unused Gas Meter Run.