

# Inspection Photos

April 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334637

Location Name: SAVAGE-67S94W/1NWNE

Inspection Document #: 702801473

Garfield County, CO

NWNE Section 1 T7S R94W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: SAVAGE-67S94W/1NWNE  
Location ID: 334637



**Photo 1.** Photo taken from the east shows an overview of the location.





Inspection Photos  
Location Name: SAVAGE-67S94W/1NWNE  
Location ID: 334637



**Photo 2.** Photos show production areas.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702801473



Inspection Photos  
Location Name: SAVAGE-67S94W/1NWNE  
Location ID: 334637



**Photo 3.** Photos show production areas.





Inspection Photos  
Location Name: SAVAGE-67S94W/1NWNE  
Location ID: 334637



**Photo 4.** Photos show a bull plug not installed on a tank drain (left) and wildlife protection BMPs in disrepair (right).



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Number: 702801473



Inspection Photos  
Location Name: SAVAGE-67S94W/1NWNE  
Location ID: 334637



**Photo 5.** Photos show examples of interim areas to the south (left) and east (right).