


**KT Resources LLC
Ant Hill Unit Wyatt-6N96W 31SWNW
Location #336470**



Lease road coming off county road 71




Access road coming off main lease road

**KT Resources LLC
Ant Hill Unit Wyatt-6N96W 31SWNW
Location #336470**




Access road to location



Entrance to location view

**KT Resources LLC
Ant Hill Unit Wyatt-6N96W 31SWNW
Location #336470**



Loadline lacking cap or plug. Drain valve not capped or plugged.



Illegible label

KT Resources LLC
Ant Hill Unit Wyatt-6N96W 31SWNW
Location #336470



Unmarked anchor



Gas meter calibration not visibly displayed

**KT Resources LLC
Ant Hill Unit Wyatt-6N96W 31SWNW
Location #336470**



Debris



Direct drainage off location. No check dam or sediment trap.

**KT Resources LLC
Ant Hill Unit Wyatt-6N96W 31SWNW
Location #336470**



Direct drainage off location. No check dams or sediment trap.

Vehicle tracking from location

**KT Resources LLC
Ant Hill Unit Wyatt-6N96W 31SWNW
Location #336470**



Apr 19, 2023 at 3:47:21 PM



Apr 19, 2023 at 3:52:07 PM

View from Northeast corner

View from Northwest corner

**KT Resources LLC
Ant Hill Unit Wyatt-6N96W 31SWNW
Location #336470**



View from Southwest corner



View from Southeast corner