

Inspection Photos

April 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334747

Location Name: SAVAGE-67S94W/1NENE

Inspection Document #: 702801479

Garfield County, CO

NENE Section 1 T7S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SAVAGE-67S94W/1NENE
Location ID: 334747



Photo 1. Photo taken from the east shows an overview of the location.

Inspection Photos
Location Name: SAVAGE-67S94W/1NENE
Location ID: 334747



Photo 2. Photos show impacted fluid within the methanol tank secondary containment. Photos also show the wire mesh wildlife protection BMP has holes in it.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 702801479

Inspection Photos
Location Name: SAVAGE-67S94W/1NENE
Location ID: 334747



Photo 3. Photos show an area at the east of the working pad area where spotted knapweed skeletons from previous years are common indicating the plant is well established on location.



Inspection Photos
Location Name: SAVAGE-67S94W/1NENE
Location ID: 334747



Photo 4. Photos show live spotted knapweed plants in the eastern interim area.

Inspection Photos
Location Name: SAVAGE-67S94W/1NENE
Location ID: 334747



Photo 5. Photo shows lack of stabilization of a portion of the working pad area.

Inspection Photos
Location Name: SAVAGE-67S94W/1NENE
Location ID: 334747



Photo 6. Photos show an example of interim areas.

