

Inspection Photos

April 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 334572

Location Name: SAVAGE-67S94W/1NESE

Inspection Document #: 702801483

Garfield County, CO

NESE Section 1 T7S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: SAVAGE-67S94W/1NESE
Location ID: 334572



Photo 1. Photo taken from the east shows an overview of the location.



Inspection Photos
Location Name: SAVAGE-67S94W/1NESE
Location ID: 334572



Photo 2. Photos show production areas.



Inspection Photos
Location Name: SAVAGE-67S94W/1NESE
Location ID: 334572



Photo 3. Photo shows the access road directly to the north of the location shows signs of lack of stabilization.



Photo 4. Photo shows lack of stabilization of the working pad.



Inspection Photos
Location Name: SAVAGE-67S94W/1NESE
Location ID: 334572



Photo 5. Photos show lack of stabilization of the working pad.



Inspection Photos
Location Name: SAVAGE-67S94W/1NESE
Location ID: 334572



Photo 6. Photos show spotted knapweed at the southeast of the location, just outside the perimeter fence but within the location disturbance.

Inspection Photos
Location Name: SAVAGE-67S94W/1NESE
Location ID: 334572



Photo 7. Photos show an example of interim areas to the east (left) and west (right).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801483