

Inspection Photos

April 17, 2023

Operator: Caerus Piceance LLC - #10456

Location ID: 323983

Location Name: SAVAGE-67S94W/1SENE

Inspection Document #: 702801485

Garfield County, CO

SENE Section 1 T7S R94W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: SAVAGE-67S94W/1SENE
Location ID: 323983



Photo 1. Photo taken from the east shows an overview of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702801485

Inspection Photos
Location Name: SAVAGE-67S94W/1SENE
Location ID: 323983



Photo 2. Photos show production areas.



Inspection Photos
Location Name: SAVAGE-67S94W/1SENE
Location ID: 323983



Photo 3. Photos show lack of stabilization of the working pad.

Inspection Photos
Location Name: SAVAGE-67S94W/1SENE
Location ID: 323983



Photo 4. Photos show an example of interim areas to the east.

