

Inspection Photos

4/17/2023

Operator: TEP ROCKY MOUNTAIN LLC #96850

Location #414268

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #414268



Photo 1: Photo 1-2 taken from the north end of the Location. Photos provide an overview of the Location from east, southeast, southwest to west.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #414268



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #414268



Photo 3: Photos 3-4 example that the perimeter fence has not been maintained in proper functioning condition; debris remains scattered throughout the interim and working pad areas.


Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC #96850

Location #414268



April 17, 2023



April 17, 2023

Photo 4: See comments under photo 3

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC #96850
Location #414268



Photo 5: Tank battery and well facility.

Operator N

850



Photo 6: Photo taken from the interim areas of the Location. Reclamation Specialist was unable to observe evidence that additional reclamation work has been performed. Vegetation observed is predominantly an annual grass monoculture.