

**Inspection Photos**  
**Location Name: Tang 1**  
**Location ID: 318635**



**Pic 1 wellhead / pump jack**



**Pic 2 tanks**

**Inspection Photos**  
**Location Name: Tang 1**  
**Location ID: 318635**



**Pic 3 Gas meter run has been removed**



**Pic 4 ECD, Separator.**