

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad

Location ID: 335197



Photo # 5896 From entrance to location



Photo # 5897 Location

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad

Location ID: 335197



Photo # 5898 Location



Photo # 5899 Location



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad

Location ID: 335197



Photo # 5901 Containment liner needs maintenance



Photo # 5902 Containment liner needs maintenance

Inspection Photos
Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad
Location ID: 335197



Apr 20, 2023 at 10:39:47 AM
CO



Apr 20, 2023 at 10:41:11 AM
CO

Photo # 5904 Meter calibration info not conspicuously posted

Photo # 5905 Meter calibration info not conspicuously posted

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad

Location ID: 335197



Photo # 5907 Erosion & Transport of sediment/Sediment encroaching on equipment



Photo # 5913 Erosion & Transport of sediment/Sediment encroaching on equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad

Location ID: 335197



Photo # 5914 Erosion & Transport of sediment/Sediment encroaching on equipment



Photo # 5915 Erosion & Transport of sediment/Sediment encroaching on equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad

Location ID: 335197



Photo # 5919 Erosion & Transport of sediment/Sediment encroaching on equipment

Photo # 5922 Erosion & Transport of sediment/Sediment encroaching on equipment

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC RMV 24-27 Pad

Location ID: 335197



Photo # 5933 Improperly marked deadman