

# TEP ROCKY MOUNTAIN LLC, GM/13-33

Location # 323902



Wellheads – Photo #02355



Chemical Tank – Photo #02358



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**TEP ROCKY MOUNTAIN LLC, GM/13-33**

# Location # 323902



## Separators – Photo #02361



## Tank Battery – Photo #02365



# TEP ROCKY MOUNTAIN LLC, GM/13-33

Location # 323902



Inadequate Berm Capacity – Photo #02367



Sediment Run-On to Location – Photo #02362



# TEP ROCKY MOUNTAIN LLC, GM/13-33

Location # 323902



**Lease Road Ditch Overrun with Sediment – Photo #02370**



**Lease Road Degradation – Photo #02372**