

TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWNE

Location # 323990



Location – Photo #02374

Wellhead – Photo #02375

TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWNE

Location # 323990



Separator – Photo #02376



Tank Battery – Photo #02377

TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWNE

Location # 323990



Apr 20, 2023 at 11:05:16
3555 CR-215
Parachute CO 81635
United States



Apr 20, 2023 at 11:07:21
3555 CR-215
Parachute CO 81635
United States

Open-Ended Load Line – Photo #02378

Lack of Stabilization – Photo #02381

TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/33SWNE

Location # 323990



Inadequate Vehicle Tracking BMP at Location Entrance/Exit – Photo #02383

Lease Road Degradation/Transport of Sediment – Photo #02384