

**Inspection Photos**  
**Location Name: DYER USX A/05-14**  
**Location #: 422852**



**Photo #1**  
**Dyer USX A 05-14 (123-33405) Wellsite**  
**Producing | PR**



**Photo #2**  
**Dyer USX A 05-14 Battery site**  
**Active**

**Inspection Photos**  
**Location Name: DYER USX A/05-14**  
**Location #: 422852**



**Photo #3**  
**Dyer USX A 05-14** Battery site  
**Active**  
*Tank(s): SE corner*




**Photo #4**  
**Dyer USX A 05-14** Battery site  
**Active**  
*Separator(s), ECD(s)*

**Inspection Photos**  
**Location Name: DYER USX A/05-14**  
**Location #: 422852**



**Photo #5**  
**Dyer USX A 05-14 Battery site**  
**Active**  
*Battery sign(s)*



**Photo #6**  
**Dyer USX A 05-14 Battery site**  
**Active**  
**CA: Gas Sales meter NOT calibrated in past year.**  
*Last documented calibration date: 12-12-2021*