

# Interim and Stormwater Inspection

April 5, 2023

Operator: Kerr McGee# 47120

Location ID: 434787

Inspection Document #:709400138

Weld County

NENW, Section 34, 1N67W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**  
**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Grenemyer 35N-3HZ  
Location ID: 434787



Photo 1. Photo taken of location signs



Inspection Photos

Location Name: Grenemyer 35N-3HZ

Location ID: 434787



**Photo 2. Photo taken of flowline scare form well heads to tank battery.**



**Photo 3. Photo of subsidence in soil in flowline scare.**



Inspection Photos

Location Name: Grenemyer 35N-3HZ

Location ID: 434787



**Photo 4. Photo taken of disturbance out of designated area, deep ruts caused by equipment.**



**Photo 5. See Photo 4 comments**

