

Interim and Stormwater Inspection

April 5, 2023

Operator: Kerr McGee# 47120

Location ID: 435007

Inspection Document #:709400144

Weld County

NENE, Section 34, 1N67W

Reed Wold
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Grenemyer 37C-3HZ
Location ID: 4435007



Photo 1. Photo taken of location signs



Inspection Photos

Location Name: Grenemyer 37C-3HZ

Location ID: 4435007



Photo 2. Photo taken of flowline scare form well heads to tank battery.

Photo 3. Photo of subsidence in soil in flowline scare.



Inspection Photos

Location Name: Grenemyer 37C-3HZ

Location ID: 4435007



Photo 4. See Photo tanken of flowline scare, from well heads to tank battery.

Photo 5. Photo taken of disturbance of vegetative area.

