

Final Reclamation Inspection

April 20, 2023

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 331380

Inspection Document #: 697504623

Weld County, CO

NESW Section 28 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DOW #23-28
Location ID: 331380



Photo 1. COGCC GISOnline aerial imagery from 2015. This inspection covers the well location, offsite tank battery and access road. The access road crossed two (2) drainages that will be addressed (orange arrows).

Inspection Photos
Location Name: DOW #23-28
Location ID: 331380



Photo 2. Photo taken from a portion of the access road, facing Southwest. Photo illustrates the access road is mostly bare that is not reflective of reference areas.



Photo 3. Photo taken from a portion of the access road, facing Northeast. See comments under Photo 2.

Inspection Photos
Location Name: DOW #23-28
Location ID: 331380



Photo 4. Photo taken from the offsite tank battery, facing East. Photo illustrates the tank battery is mostly bare that is not reflective of reference areas.



Photo 5. Photo taken from the northern drainage crossing, facing North. This area needs to be recontoured as the bottom is higher than the drainage which could impede flow.

Inspection Photos
Location Name: DOW #23-28
Location ID: 331380



Photo 6. Photo taken from the well location, facing North. Photo illustrates the well location is mostly bare with weeds that is not reflective of reference areas.



Photo 7. Photo taken from the southern drainage crossing, facing South. This area needs to be recontoured as the bottom is higher than the drainage which could impede flow.