

Final Reclamation Inspection

April 20, 2023

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 331414

Inspection Document #: 697504625

Weld County, CO

SWSE Section 28 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DOW #34-28
Location ID: 331414



Photo 1. COGCC GISOnline aerial imagery from 2015. This inspection covers the well location, offsite tank battery and access road.

Inspection Photos
Location Name: DOW #34-28
Location ID: 331414



Photo 2. Photo taken from the well/tank battery location and access road, facing East. Photo illustrates the tank battery is mostly bare that is not reflective of reference areas.



Photo 3. Photo taken from the well/tank battery location, facing South. See comments under Photo 2.