

Final Reclamation Inspection

April 20, 2023

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Location ID: 423850

Inspection Document #: 697504627

Weld County, CO

NENE Section 33 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: North Platte 44-11-28HZ
Location ID: 423850



Photo 1. COGCC GISOnline aerial imagery from 2015. This inspection covers the well location, offsite tank battery and access road.

Inspection Photos

Location Name: North Platte 44-11-28HZ

Location ID: 423850



Photo 2. Photo taken from the tank battery location and access road, facing West. Photo illustrates the tank battery and access road are mostly bare that is not reflective of reference areas.



Photo 3. Photo taken from the tank battery location, facing South. See comments under Photo 2.

Inspection Photos
Location Name: North Platte 44-11-28HZ
Location ID: 423850



Photo 4. Photo taken from the tank battery location, facing East. See comments under Photo 2.



Photo 5. Photo taken from the well location, facing South. See comments under Photo 2.

Inspection Photos
Location Name: North Platte 44-11-28HZ
Location ID: 423850



Photo 6. Photo taken from the well location, facing North. See comments under Photo 2.



Photo 7. Photo taken from the well location, facing West. See comments under Photo 2.