

Final Reclamation Inspection

April 20, 2023

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC - #8960

Well API: 123-20581

Inspection Document #: 697504633

Weld County, CO

SWnw Section 28 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: DOW #12-28
Well API: 123-20581



Photo 1. COGCC GISOnline aerial imagery from 2015. This inspection covers the well/tank battery location and access road.

Inspection Photos
Location Name: DOW #12-28
Well API: 123-20581



Photo 2. Photo taken from a portion of the access road, facing North. Photo illustrates the access road is mostly bare that is not reflective of reference areas.



Photo 3. Photo taken from a portion of the access road, facing West. See comments under Photo 2.

Inspection Photos
Location Name: DOW #12-28
Well API: 123-20581



Photo 4. Photo taken from the well location, facing West. Photo illustrates the well location is mostly bare and weeds that is not reflective of reference areas.



Photo 5. Photo taken from the well location, facing South. See comments under Photo 2.

Note- straw wattle debris.