

# CAERUS PICEANCE LLC, PUCKETT-66S96W/31NWNE

Location # 335393



Apr 24, 2023 at 13:04:07  
Parachute CO 81635  
United States



Apr 24, 2023 at 13:06:47  
Parachute CO 81635  
United States

Location Entrance – Photo #02480

Wellheads – Photo #02486

# CAERUS PICEANCE LLC, PUCKETT-66S96W/31NWN

Location # 335393



Separators – Photo #02485



Lack of Stabilization – Photo #02488

# CAERUS PICEANCE LLC, PUCKETT-66S96W/31NWN

Location # 335393



**Inadequate Vehicle Tracking BMPs at Location Entrance – Photo #02481**



**Access Road Degradation/Transportation of Sediment – Photo #02483**

# CAERUS PICEANCE LLC, PUCKETT-66S96W/31NWNE

Location # 335393



**Cut Slope Erosion onto Access Road – Photo #02479**



**Access Road Degradation/Transportation of Sediment – Photo #02498**