

Inspection Photos

Location Name: ROUSE USX A-66N64W/5SWNW

Location #: 302562



Photo #1

Rouse USX A 05-05 (123-29403) Wellsite
Temporarily Abandoned | TA



Photo #2

Rouse USX A 05-04, 05-03, 05-05, 05-06, 5-19
Battery site

Inactive | Shut-down

Equipment documented: Loc. # 302563