

Inspection Photos

Location Name: ROUSE USX A-66N64W/5SENW

Location #: 302564



Photo #1

Rouse USX A 05-06 (123-29405) Wellsite

Temporarily Abandoned | TA

CA: Valid Emergency contact info NOT posted.



Photo #2

Rouse USX A 05-04, 05-03, 05-05, 05-06, 5-19

Battery site

Inactive | Shut-down

Equipment documented: Loc. # 302563